










Fax :905-335-0327
 Phone:1-800-651-7445
 E-mail: info@fmsiinc.com
 http://www.fmsiinc.com



0108M - HOSE INLET FLEX LINE BOLT WITH GASKET ASSORTMENT

<p>5155 - BOLT 2 GM Hose Inlet Flex Line Bolt 10mm x 1.5 x 32.65mm</p>  <p>3055 - WASHER 4</p>	<p>21079 - BOLT 2 Chrysler Hose Inlet Flex Line Bolt 7/16" - 20 x 1.345</p>  <p>3048 - WASHER 4</p>	<p>21081 - BOLT 2 Chrysler Hose Inlet Flex Line Bolt 7/16" - 20 x 1.20</p>  <p>3048 - WASHER 4</p>			
<p>21082 - BOLT 2 GM Hose Inlet Flex Line Bolt 7/16" - 20 x 1.275</p>  <p>3048 - WASHER 4</p>	<p>21707 - BOLT 2 FORD Hose Inlet Flex Line Bolt 10mm x 1.0 x 1.15</p>  <p>3055 - WASHER 4</p>	<p>22453 - BOLT 2 FORD Hose Inlet Flex Line Bolt 3/8" - 24 x 1.26</p>  <p>3053 - WASHER 4</p>			
<p>H9469-2 - BOLT 2 FORD Hose Inlet Flex Line Bolt 10mm x 1.5 x 1.32mm</p> 	<p>H9449-2 - BOLT 2 GM Hose Inlet Flex Line Bolt 10mm x 1.5 x 30.58mm</p> 	<p>H9470-2 - BOLT 2 FORD Hose Inlet Flex Line Bolt 10mm x 1.5 x 1.43mm</p> 			

QTY: 54

BOLTS: 18 : WASHERS: 36

May 04 2020