













0414 - A/C TUBE END REPAIR ASSORTMENTS

<p>5171 3/8" MALE EXTERNAL O-RING TUBE REPAIR END</p>  <p>2</p>	<p>5172 3/8" MALE INTERNAL O-RING TUBE REPAIR END</p>  <p>2</p>	<p>5173 3/8" FEMALE EXTERNAL O-RING TUBE REPAIR END</p>  <p>2</p>
<p>5174 1/2" MALE EXTERNAL O-RING TUBE REPAIR END</p>  <p>2</p>	<p>5175 1/2" MALE INTERNAL O-RING TUBE REPAIR END</p>  <p>2</p>	<p>5176 1/2" FEMALE EXTERNAL O-RING TUBE REPAIR END</p>  <p>2</p>
<p>5177 5/8" MALE EXTERNAL O-RING TUBE REPAIR END</p>  <p>3</p>	<p>5178 5/8" MALE INTERNAL O-RING TUBE REPAIR END</p>  <p>2</p>	<p>5179 5/8" FEMALE EXTERNAL O-RING TUBE REPAIR END</p>  <p>2</p>
		<p>5182 3/4" FEMALE EXTERNAL O-RING TUBE REPAIR END</p>  <p>1</p>